


UTENSILI IN ACCIAIO PER TORNIO E LIMATRICE


UTENSILI PER TORNIO E LIMATRICE

■ ACS (HSS)




| REFERIMENTO | D | P | L |
|----------------|----|----|----|
| ACS - 12 222 S | 12 | 12 | 41 |
| ACS - 16 222 S | 16 | 16 | 56 |
| ACS - 18 222 S | 18 | 18 | 66 |

■ AD (HSS)




| REFERIMENTO | D | P | L |
|---------------|----|----|----|
| AD - 14 222 S | 14 | 14 | 45 |
| AD - 16 222 S | 16 | 16 | 56 |

■ DA (HSS)



| REFERIMENTO | D | P | L | E |
|---------------|----|----|-----|-----|
| DA - 16 222 S | 16 | 23 | 80 | 45° |
| DA - 18 222 S | 18 | 27 | 90 | 45° |
| DA - 22 222 S | 22 | 29 | 100 | 45° |

■ DA (MD)



| REFERIMENTO | D | L | P PLACCHETTA | E | PTR |
|-------------|----|----|-----------------|-----|-----|
| DA - 12 | 12 | 60 | DA 12 | 40° | |
| DA - 14 | 14 | 70 | DA 14 | 40° | |
| DA - 16 | 16 | 80 | DA 16 | 40° | |
| DA - 18 | 18 | 90 | DA 18 | 40° | |